

About Technology Integrators

Signature Log Clamp >

Signature Log Vacuum Lift >

Pressroom Tools

Continuous Dampening System

Lift Table & Palletizers >

Ink Metering System

About Air Stamping

M-1000 Series Press Parts >

M-110 Series Press Parts >

Other Press Parts >

Folder Parts >

Segmented Ink Blades

Double Wall Water Pans

Automatic Ink Levelers >

Tradeshows Highlights


E-News Letter Library >

Streaming Video Library >

Contact Us

www.technologyintegrators.net

www.airstamping.com

217-342-3981 




Technology
Integrators

AIR STAMPING INC.

E-NEWS - VOLUME 1-08

M1000 2 PIECE REEL ROD STUDS

Broken reel rod stud?
No time to pull cylinder to fix?
Need to be back in production quickly?
AIR STAMPING HAS A SOLUTION!



ASI has designed a 2 piece reel rod stud(2PS) that should be in every maintenance or pressroom manager's drawer. The 2PS allows the press to get back into production quickly, without having to pull the cylinder to replace the broken stud. This stud is offered for both the ASI and Goss plate and blanket stud designs. The 2PS is not designed as a permanent fix. We recommend replacing when the schedule allows with the original 1 piece stud..